



# Intel® Pentium® 4 Processor 6x1 <sup>Δ</sup> Sequence

## Specification Update

---

*– On 65 nm Process in the 775-land LGA Package and supporting  
Intel® Extended Memory 64 Technology<sup>φ</sup>*

*February 2006*

**Notice:** The Intel® Pentium® 4 processor 6x1 sequence on 65 nm may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are documented in this Specification Update.



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® Pentium® 4 Processor may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

<sup>1</sup>Hyper-Threading Technology requires a computer system with an Intel® processor supporting HT Technology and a Hyper-Threading Technology enabled chipset, BIOS and operating system. Performance will vary depending on the specific hardware and software you use. See <<<http://www.intel.com/info/hyperthreading/>>> for more information including details on which processors support HT Technology.

Φ Intel® Extended Memory 64 Technology (Intel® EM64T) requires a computer system with a processor, chipset, BIOS, operating system, device drivers and applications enabled for Intel EM64T. Processor will not operate (including 32-bit operation) without an Intel EM64T-enabled BIOS. Performance will vary depending on your hardware and software configurations. See [www.intel.com/info/em64t](http://www.intel.com/info/em64t) for more information including details on which processors support EM64T or consult with your system vendor for more information.

<sup>4</sup>Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. Over time processor numbers will increment based on changes in clock, speed, cache, FSB, or other features, and increments are not intended to represent proportional or quantitative increases in any particular feature. Current roadmap processor number progression is not necessarily representative of future roadmaps. See [www.intel.com/products/processor\\_number](http://www.intel.com/products/processor_number) for details.

Enabling Execute Disable Bit functionality requires a PC with a processor with Execute Disable Bit capability and a supporting operating system. Check with your PC manufacturer on whether your system delivers Execute Disable Bit functionality.

Intel, Pentium, Celeron, Intel Xeon, Pentium II Xeon, Pentium III Xeon, Intel NetBurst and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2006, Intel Corporation



## Contents

---

Revision History .....	4
Preface .....	5
Summary Tables of Changes .....	7
General Information .....	10
Identification Information .....	11
Errata.....	13
Specification Changes .....	20
Specification Clarifications .....	21
Documentation Changes .....	22

## Revision History

---

Version	Description	Date
-001	Initial release	January 2006
-002	Updated related documents, updated processor identification table, and updated figure 1.	February 2006

§

## Preface

This document is an update to the specifications contained in the documents listed in the following Affected Documents/Related Documents table. It is a compilation of device and document errata and specification clarifications and changes, and is intended for hardware system manufacturers and for software developers of applications, operating systems, and tools.

Information types defined in the Nomenclature section of this document are consolidated into this update document and are no longer published in other documents. This document may also contain information that has not been previously published.

## Affected Documents

Document Title	Document Number
<i>Intel® Pentium® 4 Processor 6x1<sup>4</sup> Sequence Datasheet</i>	310308-001

## Related Documents

Document Title	Document Number
<i>IA-32 Intel® Architecture Software Developer's Manual Volume 1: Basic Architecture, document 253665</i>	<a href="http://developer.intel.com/design/pentium4/manuals/index_new.htm">http://developer.intel.com/design/pentium4/manuals/index_new.htm</a>
<i>IA-32 Intel® Architecture Software Developer's Manual Volume 2A: Instruction Set Reference Manual A–M, document 253666</i>	
<i>IA-32 Intel® Architecture Software Developer's Manual Volume 2B: Instruction Set Reference Manual, N–Z, document 253667</i>	
<i>IA-32 Intel Architecture Software Developer's Manual Volume 3A: System Programming Guide, document 253668</i>	
<i>IA-32 Intel Architecture Software Developer's Manual Volume 3B: System Programming Guide, document 253669</i>	

## Nomenclature

**S-Spec Number** is a five-digit code used to identify products. Products are differentiated by their unique characteristics (e.g., core speed, L2 cache size, package type, etc.) as described in the processor identification information table. Care should be taken to read all notes associated with each S-Spec number

**QDF Number** is a several digit code that is used to distinguish between engineering samples. These processors are used for qualification and early design validation. The functionality of these parts can range from mechanical only to fully functional. The NDA specification update has a processor identification information table that lists these QDF numbers and the corresponding product sample details.

**Errata** are design defects or errors. Errata may cause the processor's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

# Summary Tables of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications or Documentation Changes that apply to the listed component steppings. Intel intends to fix some of the errata in a future stepping of the component, and to account for the other outstanding issues through documentation or Specification Changes as noted. This table uses the following notations:

## Codes Used in Summary Table

### Stepping

X:	Erratum, Specification Change or Clarification that applies to this stepping.
(No mark) or (Blank Box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

### Status

Doc:	Document change or update that will be implemented.
PlanFix:	This erratum may be fixed in a future stepping of the product.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Shaded:	This item is either new or modified from the previous version of the document.

**Note:** Each Specification Update item is prefixed with a capital letter to distinguish the product. The key below details the letters that are used in Intel's microprocessor Specification Updates:

- A = Intel® Pentium® II processor
- B = Mobile Intel® Pentium® II processor
- C = Intel® Celeron® processor
- D = Intel® Pentium® II Xeon® processor
- E = Intel® Pentium® III processor
- F = Intel® Pentium® processor Extreme Edition
- G = Intel® Pentium® III Xeon® processor
- H = Mobile Intel® Celeron® processor at 466 MHz, 433 MHz, 400 MHz, 366 MHz, 333 MHz, 300 MHz, and 266 MHz
- K = Mobile Intel® Pentium® III Processor – M
- L = Intel® Celeron® D processor

M = Mobile Intel® Celeron® processor  
 N = Intel® Pentium® 4 processor  
 O = Intel® Xeon® processor MP  
 P = Intel® Xeon® processor  
 Q = Mobile Intel® Pentium® 4 processor supporting Hyper-Threading Technology on 90-nm process technology  
 R = Intel® Pentium® 4 processor on 90 nm process  
 S = 64-bit Intel® Xeon® Processor with 800 MHz system bus  
 T = Mobile Intel® Pentium® 4 processor – M  
 U = 64-bit Intel® Xeon® processor MP with up to 8MB L3 Cache  
 V = Mobile Intel® Celeron® processor on 0.13 Micron Process in Micro-FCPGA Package  
 W = Intel® Celeron® M processor  
 X = Intel® Pentium® M processor on 90 nm process with 2-MB L2 cache  
 Y = Intel® Pentium® M processor  
 Z = Mobile Intel® Pentium® 4 processor with 533 MHz system bus

NO	B1	Plan	ERRATA
AB1	X	No Fix	Locks and SMC Detection May Cause the Processor to Temporarily Hang
AB2	X	No Fix	Memory Aliasing of Pages as Uncacheable Memory Type and Write Back (WB) May Hang the System
AB3	X	No Fix	Data Breakpoints on the High Half of a Floating Point Line Split may not be Captured
AB4	X	No Fix	MOV CR3 Performs Incorrect Reserved Bit Checking When in PAE Paging
AB5	X	No Fix	Incorrect Access Controls to MSR_LASTBRANCH_0_FROM_LIP MSR Registers
AB6	X	No Fix	FXRSTOR May Not Restore Non-canonical Effective Addresses on Processors with Intel® Extended Memory 64 Technology (Intel® EM64T) Enabled
AB7	X	No Fix	A Push of ESP that Faults may Zero the Upper 32 Bits of RSP
AB8	X	No Fix	Checking of Page Table Base Address May Not Match the Address Bit Width Supported by the Platform
AB9	X	No Fix	With TF (Trap Flag) Asserted, FP Instruction That Triggers an Unmasked FP Exception May Take Single Step Trap Before Retirement of Instruction
AB10	X	No Fix	BTS(Branch Trace Store) and PEBS(Precise Event Based Sampling) May Update Memory outside the BTS/PEBS Buffer
AB11	X	No Fix	Control Register 2 (CR2) Can be Updated during a REP MOVS/STOS Instruction with Fast Strings Enabled
AB12	X	No Fix	REP STOS/MOVS Instructions with RCX $\geq 2^{32}$ May Cause a System Hang
AB13	X	No Fix	A 64-Bit Value of Linear Instruction Pointer (LIP) May be Reported Incorrectly in the Branch Trace Store (BTS) Memory Record or in the Precise Event Based Sampling (PEBS) Memory Record
AB14	x	No Fix	Two Correctable L2 Cache Errors in Close Proximity May Cause a System Hang
AB15	x	No Fix	Processor May Hang with a 25% or Less STPCLK# Duty Cycle



NO	B1	Plan	ERRATA
AB16	X	No Fix	Machine Check Exceptions May not Update Last-Exception Record MSRs (LERs)
AB17	x	No Fix	Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt
AB18	x	PlanFix	At a Bus Ratio of 13:1, RCNT and Address Parity May be Incorrect
AB19	x	PlanFix	During an Enhanced HALT, Enhanced Intel® SpeedStep® Technology, or Thermal Monitor 2 Ratio Transition the System May Hang


Number	Plan	SPECIFICATION CHANGES
		There are no Specification Changes in this Specification Update revision

Number	Plan	SPECIFICATION CLARIFICATIONS
		There are no Specification Clarification in this Specification Update revision

Number	Plan	DOCUMENTATION CHANGES
		There are no Documentation Changes in this Specification Update revision.

## General Information

**Figure 1. Intel® Pentium® 4 Processor 6x1 Sequence on 65 nm process Package (Top Markings)**



# Identification Information

The Intel® Pentium® 4 processor 6x1 sequence may be identified by the following values:

Family <sup>1</sup>	Model <sup>2</sup>
1111b	0110b

## NOTES:

1. The Family corresponds to bits [11:8] of the EDX register after RESET, bits [11:8] of the EAX register after the CUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
2. The Model corresponds to bits [7:4] of the EDX register after RESET, bits [7:4] of the EAX register after the CUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CUID instruction is executed with a 2 in the EAX register. Refer to the *Intel Processor Identification and the CUID Instruction Application Note* (AP-485) for further information on the CUID instruction.

**Table 1. Intel® Pentium® 4 Processor 6x1 Sequence Identification Information**

S-Spec	Core Stepping	L2 Cache Size (bytes)	Processor Signature	Processor Number	Speed Core/Bus	Package and Revision	Notes
SL8WJ	B1	2M	0F62h	631	3GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 2, 3
SL8WH	B1	2M	0F62h	641	3.2GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 2, 3
SL8WG	B1	2M	0F62h	651	3.4GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 2, 3
SL8WF	B1	2M	0F62h	661	3.6GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 2, 3
SL94Y	B1	2M	0F62h	631	3GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 3, 4
SL94X	B1	2M	0F62h	641	3.2GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 3, 4
SL94W	B1	2M	0F62h	651	3.4GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 3, 4


**Table 1. Intel® Pentium® 4 Processor 6x1 Sequence Identification Information**

S-Spec	Core Stepping	L2 Cache Size (bytes)	Processor Signature	Processor Number	Speed Core/Bus	Package and Revision	Notes
SL94V	B1	2M	0F62h	661	3.6GHz/800MHz	775-land FC-LGA6 37.5 x 37.5 mm Rev 01	1, 3, 4

**NOTES:**

1. These processors support the 775\_VR\_CONFIG\_05A (mainstream) specifications.
2. These parts support Enhanced Intel SpeedStep® technology.
3. These parts support Hyper-Threading Technology.
4. These parts do NOT support Enhanced Intel SpeedStep® technology, Enhanced HALT State, or Thermal Monitor 2.

## Errata

---

### AB1. Bus Locks and SMC Detection May Cause the Processor to Hang Temporarily

**Problem:** The processor may temporarily hang in an HT Technology enabled system if one logical processor executes a synchronization loop that includes one or more locks and is waiting for release by the other logical processor. If the releasing logical processor is executing instructions that are within the detection range of the self-modifying code (SMC) logic, then the processor may be locked in the synchronization loop until the arrival of an interrupt or other event.

**Implication:** If this erratum occurs in an HT Technology enabled system, the application may temporarily stop making forward progress. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### AB2. Memory Aliasing of Pages As Uncacheable Memory Type and Write Back (WB) May Hang the System

**Problem:** When a page is being accessed as either Uncacheable (UC) or Write Combining (WC) and WB, under certain bus and memory timing conditions, the system may loop in a continual sequence of UC fetch, implicit writeback, and Request For Ownership (RFO) retries.

**Implication:** This erratum has not been observed in any commercially available operating system or application. The aliasing of memory regions, a condition necessary for this erratum to occur, is documented as being unsupported in the *IA-32 Intel® Architecture Software Developer's Manual*, Volume 3, section 10.12.4, Programming the PAT. However, if this erratum occurs the system may hang.

**Workaround:** The pages should not be mapped as either UC or WC and WB at the same time.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**AB3. Data Breakpoints on the High Half of a Floating Point Line Split May Not Be Captured**

**Problem:** When a floating point load which splits a 64-byte cache line gets a floating point stack fault, and a data breakpoint register maps to the high line of the floating point load, internal boundary conditions exist that may prevent the data breakpoint from being captured.

**Implication:** When this erratum occurs, a data breakpoint will not be captured.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**AB4. MOV CR3 Performs Incorrect Reserved Bit Checking When in PAE Paging**

**Problem:** The MOV CR3 instruction should perform reserved bit checking on the upper unimplemented address bits. This checking range should match the address width reported by CPUID instruction 0x8000008. This erratum applies whenever PAE is enabled.

**Implication:** Software that sets the upper address bits on a MOV CR3 instruction and expects a fault may fail. This erratum has not been observed with commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**AB5. Incorrect Access Controls to MSR\_LASTBRANCH\_0\_FROM\_LIP MSR Registers**

**Problem:** When an access is made to the MSR\_LASTBRANCH\_0\_FROM\_LIP MSR register, an expected #GP fault may not happen.

**Implication:** A read of the MSR\_LASTBRANCH\_0\_FROM\_LIP MSR register may not cause a #GP fault.

**Workaround:** None identified

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## AB6. FXRSTOR May Not Restore Non-canonical Effective Addresses on Processors with Intel® Extended Memory 64 Technology (Intel® EM64T) Enabled

**Problem:** If an x87 data instruction has been executed with a non-canonical effective address, FXSAVE may store that non-canonical FP Data Pointer (FDP) value into the save image. An FXRSTOR instruction executed with 64-bit operand size may signal a General Protection Fault (#GP) if the FDP or FP Instruction Pointer (FIP) is in non-canonical form.

**Implication:** When this erratum occurs, Intel EM64T enabled systems may encounter an unintended #GP fault.

**Workaround:** Software should avoid using non-canonical effective addressing in EM64T enabled processors. BIOS can contain a workaround for this erratum removing the unintended #GP fault on FXRSTOR.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## AB7. A Push of ESP That Faults May Zero the Upper 32 Bits of RSP

**Problem:** In the event that a push ESP instruction, that faults, is executed in compatibility mode, the processor will incorrectly zero upper 32-bits of RSP.

**Implication:** A Push of ESP in compatibility mode will zero the upper 32-bits of RSP. Due to this erratum, this instruction fault may change the contents of RSP. This erratum has not been observed in commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## AB8. Checking of Page Table Base Address May Not Match the Address Bit Width Supported by the Platform

**Problem:** If the page table base address, included in the page map level-4 table, page-directory pointer table, page-directory table or page table, exceeds the physical address range supported by the platform (e.g., 36-bit) and it is less than the implemented address range (e.g., 40-bit), the processor does not check if the address is invalid.

**Implication:** If software sets such invalid physical address in those tables, the processor does not generate a page fault (#PF) upon access to that virtual address, and the access results in an incorrect read or write. If BIOS provides only valid physical address ranges to the operating system, this erratum will not occur.

**Workaround:** BIOS must provide valid physical address ranges to the operating system.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**AB9. With TF (Trap Flag) Asserted, FP Instruction That Triggers an Unmasked FP Exception May Take Single Step Trap before Retirement of Instruction**

**Problem:** If an FP instruction generates an unmasked exception with the EFLAGS.TF=1, it is possible for external events to occur, including a transition to a lower power state. When resuming from the lower power state, it may be possible to take the single step trap before the execution of the original FP instruction completes.

**Implication:** A Single Step trap will be taken when not expected.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

**AB10. BTS(Branch Trace Store) and PEBS(Precise Event Based Sampling) May Update Memory outside the BTS/PEBS Buffer**

**Problem:** If the BTS/PEBS buffer is defined such that:

- The difference between BTS/PEBS buffer base and BTS/PEBS absolute maximum is not an integer multiple of the corresponding record sizes
- BTS/PEBS absolute maximum is less than a record size from the end of the virtual address space
- The record that would cross BTS/PEBS absolute maximum will also continue past the end of the virtual address space

A BTS/PEBS record can be written that will wrap at the 4G boundary (IA32) or 2<sup>64</sup> boundary (EM64T mode), and write memory outside of the BTS/PEBS buffer.

**Implication:** Software that uses BTS/PEBS near the 4G boundary (IA32) or 2<sup>64</sup> boundary (EM64T mode), and defines the buffer such that it does not hold an integer multiple of records can update memory outside the BTS/PEBS buffer.

**Workaround:** Define BTS/PEBS buffer such that BTS/PEBS absolute maximum minus BTS/PEBS buffer base is integer multiple of the corresponding record sizes as recommended in the IA-32 Intel<sup>®</sup> Architecture Software Developer's Manual, Volume 3.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



# **AB11. Control Register 2 (CR2) Can be Updated during a REP MOVStOS Instruction with Fast Strings Enabled**

**Problem:** Under limited circumstances while executing a REP MOVStOS string instruction, with fast strings enabled, it is possible for the value in CR2 to be changed as a result of an interim paging event, normally invisible to the user. Any higher priority architectural event that arrives and is handled while the interim paging event is occurring may see the modified value of CR2.

**Implication:** The value in CR2 is correct at the time that an architectural page fault is signaled. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

# **AB12. REP StOS/MOVSt Instructions with RCX >= 2^32 May Cause a System Hang**

**Problem:** In IA-32e mode using Intel EM64T-enabled processors, executing a repeating string instruction with the iteration count greater than or equal to 2^32 and a pending event may cause the REP StOS/MOVSt instruction to live lock and hang.

**Implication:** When this erratum occurs, the processor may live lock and result in a system hang. Intel has not observed this erratum with any commercially available software.

**Workaround:** Do not use strings larger than 4 GB.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

# **AB13. A 64-Bit Value of Linear Instruction Pointer (LIP) May be Reported Incorrectly in the Branch Trace Store (BTS) Memory Record or in the Precise Event Based Sampling (PEBS) Memory Record**

**Problem:** On a processor supporting Intel® EM64T,

- If an instruction fetch wraps around the 4G boundary in Compatibility Mode, the 64-bit value of LIP in the BTS memory record will be incorrect (upper 32 bits will be set to FFFFFFFFh when they should be 0).
- If a PEBS event occurs on an instruction whose last byte is at memory location FFFFFFFFh, the 64-bit value of LIP in the PEBS record will be incorrect (upper 32 bits will be set to FFFFFFFFh when they should be 0).

**Implication:** Intel has not observed this erratum on any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

# **AB14. Two Correctable L2 Cache Errors in Close Proximity May Cause a System Hang**

**Problem:** If two correctable L2 cache errors are detected in close proximity to each other, a livelock may occur as a result of the processor being unable to resolve this condition.

**Implication:** When this erratum occurs, the processor may livelock and result in a system hang. Intel has only observed this erratum while injecting cache errors in simulation..

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AB15. Processor May Hang with a 25% or Less STPCLK# Duty Cycle**

**Problem:** If a system de-asserts STPCLK# at a 25% or less duty cycle and the processor thermal control circuit (TCC) on-demand clock modulation is active, the processor may hang. This erratum does not occur under the automatic mode of the TCC.

**Implication:** When this erratum occurs, the processor may hang.

**Workaround:** If use of the on-demand mode of the processor's TCC is desired in conjunction with STPCLK# modulation, then assure that STPCLK# is not asserted at a 25% duty cycle.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AB16. Machine Check Exceptions May not Update Last-Exception Record MSRs (LERs)**

**Problem:** If a system de-asserts STPCLK# at a 25% or less duty cycle and the processor thermal control circuit (TCC) on-demand clock modulation is active, the processor may hang. This erratum does not occur under the automatic mode of the TCC.

**Implication:** When this erratum occurs, the LER may not contain information relating to the machine check exception. They will contain information relating to the exception prior to the machine check exception

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

# **AB17. Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt**

**Problem:** If a local interrupt is pending when the LVT entry is written, an interrupt may be taken on the new interrupt vector even if the mask bit is set.

**Implication:** An interrupt may immediately be generated with the new vector when a LVT entry is written, even if the new LVT entry has the mask bit set. If there is no Interrupt Service Routine (ISR) set up for that vector the system will GP fault. If the ISR does not do an End of Interrupt (EOI) the bit for the vector will be left set in the in-service register and mask all interrupts at the same or lower priority.

**Workaround:** Any vector programmed into an LVT entry must have an ISR associated with it, even if that vector was programmed as masked. This ISR routine must do an EOI to clear any unexpected interrupts that may occur. The ISR associated with the spurious vector does not generate an EOI, therefore the spurious vector should not be used when writing the LVT.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

# **AB18. At a Bus Ratio of 13:1, RCNT and Address Parity May be Incorrect**

**Problem:** In a system running at the 13:1 bus ratio, RCNT[0] ( ADDR# [28], phase b) may report incorrect information.

**Implication:** RCNT[0] may contain incorrect information and cause address parity machine check errors.

**Workaround:** Address parity should be disabled and RCNT information should be ignored at the bus ratio of 13:1.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

# **AB19. During an Enhanced HALT, Enhanced Intel® SpeedStep® Technology, or Thermal Monitor 2 Ratio Transition the System May Hang**

**Problem:** The BNR signal may not function properly during an Enhanced HALT, Enhanced Intel® SpeedStep technology, or Thermal Monitor 2 ratio transition.

**Implication:** The system may hang due to incorrect BNR signaling.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## Specification Changes

---

The Specification Changes listed in this section apply to the following documents:

- *Intel® Pentium® 4 Processor 6x1<sup>A</sup> Sequence Datasheet*

All Specification Changes will be incorporated into a future version of the appropriate Pentium® 4 processor documentation.

∆ Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. Over time processor numbers will increment based on changes in clock, speed, cache, FSB, or other features, and increments are not intended to represent proportional or quantitative increases in any particular feature. Current roadmap processor number progression is not necessarily representative of future roadmaps. See [www.intel.com/products/processor\\_number](http://www.intel.com/products/processor_number) for details.

§

## Specification Clarifications

---

The Specification Clarifications listed in this section apply to the following documents:

- *Intel® Pentium® 4 Processor 6x1<sup>A</sup> Sequence Datasheet*

All Specification Clarifications will be incorporated into a future version of the appropriate Pentium® 4 processor 6x1 sequence documentation.

§

## Documentation Changes

---

The Documentation Changes listed in this section apply to the following documents:

- *Intel® Pentium® 4 Processor 6x1<sup>A</sup> Sequence Datasheet*

All Documentation Changes will be incorporated into a future version of the appropriate Pentium® 4 processor 6x1 sequence documentation.

**Note: Documentation changes for IA-32 Intel® Architecture Software Developer's Manual volumes 1, 2A, 2B, 3A, and 3B will be posted in a separate document IA-32 Intel® Architecture Software Developer's Manual Documentation Changes. Follow the link below to become familiar with this file.**

<http://developer.intel.com/design/pentium4/specupdt/252046.htm>

There are no documentation changes in this Specification Update revision.

§